

Milling, drilling and countersinking tools

Safety notes

- For safety reasons, the maximum permitted rotational speed indicated must never be exceeded.



Wear eye protection!



Wear hearing protection!



Wear a dust mask!



Wearing protective gloves is recommended. Handle the tool drive with both hands.



Observe the recommended rotational speed, especially when using burrs with long shanks!



Observe the contact angle of 5–60° (**ALUMASTER HSD-F!**)



Tighten the bolts!



Do not use if damaged!



Do not use for cutting!



CE-marked